

EUTROPHICATION in the Millstone WMA



The Cranbury Brook Impoundment under Route 130 provides ideal conditions for algal and plant growth.



Excessive macrophyte growth is prevalent in the Upper Millstone River.



Excessive algae and macrophyte growth mix with the detritus from Hurricane Floyd at the Kingston Lock.